
Annex H2

Transplanted Plant Species of Conservation Importance Monitoring





1st Root Prunning for G62RT07



1st Root Prunning for G62RT08







Backfilled with soil mix-A



Backfilled with soil mix-B



Watering-A



Watering-B

Date of 1st stage root pruning: 22 Dec 2021 Date of 2nd stage root pruning: 6 Jan 2022 Date of transplantation: 21 Jan 2022





Fixing Bamboo Stakes-A

Fixing Bamboo Stakes-B



2nd Root Prunning for G62RT07



2nd Root Prunning for G62RT08



Date of 1st stage root pruning: 22 Dec 2021 Date of 2nd stage root pruning: 6 Jan 2022 Date of transplantation: 21 Jan 2022



Depth of rootball for G62RT07



Depth of rootball for G62RT08



Watering-A





3rd Root Prunning for G62RT07

Date of 1st stage root pruning: 22 Dec 2021 Date of 2nd stage root pruning: 6 Jan 2022 Date of transplantation: 21 Jan 2022



3rd Root Prunning for G62RT08



Depth of rootball for G62RT07

Depth of rootball for G62RT08

Date of 1st stage root pruning: 22 Dec 2021 Date of 2nd stage root pruning: 6 Jan 2022 Date of transplantation: 21 Jan 2022



Watering-A

Watering-B

Date of 1st stage root pruning: 22 Dec 2021 Date of 2nd stage root pruning: 6 Jan 2022 Date of transplantation: 21 Jan 2022





Tied with coir mat for root ball

Tied with triple twist wire mesh





Lifing the tree-B



Lifing and Transplanting for G62RT07



Lifing and Transplanting for G62RT08





Tree planting in the final location-G62TR07




Tree planting in the final location-G62TR08

Photo 01: Tree tag of G62/ RT-07	Photo 02:Tree crown of G62/ RT-07
Photo 02 Minute view of 022/15.25	Not used
Photo 03: Whole view of G62/RT-07	

Photo 04: Tree tag of G62/ RT-08	Photo 05: Root collar of G62/RT-08
Photo 06: Crown condition of G62/RT-08	Photo 07: Crown condition of G62/RT-08


Inspection date: 11 Mar 2022






Inspection date: 16 Mar 2022






Inspection date: 23 Mar 2022





Inspection date: 30 Mar 2022

Photo 32: Root collar of G62/ RT-07	Photo 33: Crown condition of G62/RT-07
<image/>	
Photo 34: Crown condition of G62/RT-07	Photo 35:Trunk condition for G62/RT-07





PROJECT

TUNG CHUNG NEW TOWN EXTENSION (EAST) -DESIGN AND CONSTRUCTION

CLIENT



土木工程拓展署 CEDD Civil Engineering and Development Department

CONSULTANT

AECOM Asia Company Ltd. www.aecom.com

SUB-CONSULTANTS

ISSUE/REVISION

Α	NOV. 20	REVISED LAYOUT	CC
-	OCT. 20	FIRST ISSUE	CC
l/R 修訂	DATE ^{日期}	DESCRIPTION 内容摘要	CHK. 複核


STATUS

DIMENSION UNIT

SCALE A11:500

METRES

KEY PLAN A1 1:20000



PROJECT NO.

CONTRACT NO.

60507694

CE 69/2015 (CE)

SHEET TITLE

LOCATION OF RECEPTOR SITE FOR THE TRANSPLANTED PLANTS OF CONSERVATION IMPORTANCE

SHEET NUMBER

60507694/Z47/FIGURE 3