



## ANNEX J LANDSCAPE AND VISUAL MONITORING



## ANNEX J1

## EXAMPLES OF LANDSCAPE AND VISUAL MITIGATION MEASURES



Photo 1 – Tree protection zone for preserved plant species of conservation importance



Photo 2 – General view of compensation woodland



Photo 3 – Erection of site hoardings in unobtrusive colours



Photo 4 – Natural Rock Material/Planting for Artificial Seawall



Photo 5 – Orientation of night time lighting to minimize glare impact



ANNEX J2

EVENT AND ACTION PLAN FOR  
LANDSCAPE AND VISUAL MITIGATION  
MEASURES

**Annex J2**      **Event and Action Plan for Landscape and Visual**

| Event                          | Action                                                                                                                                                                                                                                                                                     |                                                                                                                                                                                                                                              |                                                                                                                                                                                                    |                                                                                                                                                                                                                                                                      |
|--------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                                | ET                                                                                                                                                                                                                                                                                         | IEC                                                                                                                                                                                                                                          | ER                                                                                                                                                                                                 | Contractor                                                                                                                                                                                                                                                           |
| Design Check                   | 1. Check final design conforms to the requirements of EP and prepare report.                                                                                                                                                                                                               | 1. Check report.<br>2. Recommend remedial design if necessary.                                                                                                                                                                               | 1. Undertake remedial design if necessary.                                                                                                                                                         |                                                                                                                                                                                                                                                                      |
| Non-conformity on one occasion | 1. Inform the IEC, ER and the Contractor<br>2. Discuss remedial actions with IEC, ER and Contractor<br>3. Monitor remedial actions until rectification has been completed                                                                                                                  | 1. Check report.<br>2. Check Contractor's working method<br>3. Discuss with ET, ER and Contractor on possible remedial measures.<br>4. Advise ER on effective of proposed remedial measures.<br>5. Check implementation of remedial measures | 1. Confirm receipt of notification of non-conformity in writing<br>2. Review and agree on the remedial measures proposed by the Contractor<br>3. Ensure remedial measures are properly implemented | 1. Identify source and investigate the non-conformity<br>2. Amend working methods agreed with ER as appropriate<br>3. Rectify damage and undertake any necessary replacement                                                                                         |
| Repeated Non-conformity        | 1. Identify sources<br>2. Inform the Contractor, IEC and ER<br>3. Discuss inspection frequency<br>4. Discuss remedial actions with IEC, ER and Contractor<br>5. Monitor remedial actions until rectification has been completed<br>6. If non-conformity stops, cease additional monitoring | 1. Check inspection report<br>2. Check Contractor's working method<br>3. Discuss with ET, ER and Contractor on possible remedial measures<br>4. Advise ER on effectiveness of proposed remedial measures                                     | 1. Notify the Contractor<br>2. In consultation with the ET and IEC, agree with the Contractor on the remedial measures to be implemented<br>3. Supervise implementation of remedial measures       | 1. Identify source and investigate the non-conformity<br>2. Amend working methods agreed with ER as appropriate<br>3. Rectify damage and undertake any necessary replacement. Stop relevant portion of works as determined by ER until the non-conformity is abated. |